

R0015034B ZX5 Module B Wiring Loom installation Part 2

Installation steps for Electrical looms installation into Module B

 Difficulty **Hard**

 Duration **1 minute(s)**

Contents

Introduction

Step 1 - Unless otherwise stated

Step 2 - Connect 20B

Step 3 - Connect 21B

Step 4 - Connect 22B

Step 5 - Connect 23B

Step 6 - Loom 24B

Step 7 - Route X53 Z axis Datum

Step 8 - Route X488 and X56

Step 9 - Route X50

Step 10 - X65 CLISHm

Step 11 - X63 CLITHm

Step 12 - X59 X61

Step 13 - Route X247

Step 14 - Route X111 and X112

Step 15 - Route X459 and X460

Step 16 - X120 VY Datum

Step 17 - Route ring power Cables Z105 onwards

Comments

Introduction

Parts Required

Pre labelled Wiring loom assembly R0015034B from electrical team

Tools required

Flush cutters

Tie wraps small

Tie Wraps Large

Step 1 - Unless otherwise stated

All bolts to have Loctite 243 adhesive applied unless otherwise stated


All Threaded Pneumatic connections to have Loctite 570 applied

All bolts to be pen marked once adhesive applied and correct tension added



Step 2 - Connect 20B

Connect cable 20b to in port on Fb01B and route as shown





Step 3 - Connect 21B

Connect 21b To FB01B out port to FB02B in port , routing as shown





Step 4 - Connect 22B

Connect 22b To FB02B out port to FB03B in port , routing as shown




Step 5 - Connect 23B

Connect 23b To FB03B out port to FB04B in port , routing as shown




Step 6 - Loom 24B


Retrieve 24B cable which exits the rotary head energy chain and loom to box FB04B out port



Step 7 - Route X53 Z axis Datum

Route X53 cable as shown, to EC04B






Step 8 - Route X488 and X56

Retrieve X488 and X56 from rotary ring loom and route around trunking to EC04B





Step 9 - Route X50

Retrieve X50 from energy chain rear and route as shown, exiting at FB04B






Step 10 - X65 CLISHm

Route reed switch X65 as shown. Finish at FB04B

Ensure maximum length is left for routing to cylinder at a later point


i ...L-R machines Require extension cable to allow correct routing. See electrical team for additional cable. Cable join/plug must be left in vertical trunking for ease of access





Step 11 - X63 CLITHm



Route X63 reed switch to the route shown, leaving minimal cable for termination at FB04B end





Step 12 - X59 X61

Route reed switches X59 and X61 from FB04B to exit at point shown of trunking

Ensure minimal length of cable is left at FB04B termination end







Step 13 - Route X247

Connect X247 from loom box onto V safe sensor and route as shown to FB01B








Step 14 - Route X111 and X112



Route X111 and X112 reed switches from loom box and route as shown

Reed switches to exit same side as cylinders for V notch clamps

Ensure minimal cable length is left at FB01B connection end

Coil reed switches onto cylinder for temporary measure







Step 15 - Route X459 and X460



Route fitted reed switches X459 and X460 to FB01B

Ensure spiral wrap is used and routed as shown



Step 16 - X120 VY Datum

Connect X120 VY datum cable from wiring loom to sensor shown . Leave trailing ready for looming



Step 17 - Route ring power Cables Z105 onwards

Route power cables from ring and exit as shown for Z105 and later

Z104 will have green power cable instead of grey, and single earth cable , route same as above



