

Common Issue - ZX5 Servo cable rubbing on energy train tray

ZX5 Servo cable rubbing on energy train tray

Contents

Problem .

Comments

Problem .

Premature wear on SX/GX Axis energy chain.