


Fichier:Reinforcing Forward Clamp Energy Chain System 3.png


Energy chain tray stress fracture on 421312



Size of this preview: 359 × 599 pixels.
Original file (592 × 987 pixels, file size: 435 KB, MIME type: image/png)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	14:18, 27 October 2023		592 × 987 (435 KB)	Gareth Green (talk contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

Stuertz Infeed - Reinforcing Forward Clamp Energy Chain System

Metadata

This file contains additional information, probably added from the digital camera or scanner used to create or digitize it. If the file has been modified from its original state, some details may not fully reflect the modified file.

Horizontal resolution	37.79 dpc
-----------------------	-----------

Vertical resolution	37.79 dpc
---------------------	-----------