

Make Backup Image of CNC PC

Generate a backup image of the Front End PC to extra Hard disk

 Difficulty Easy

 Duration 20 minute(s)

Contents

Introduction
Step 1 - Imaging
Comments

Introduction

Each CNC PC comes with a USB Backup Stick.

This is for those machines that have an Extra disk (D:) (normally used for the Virtual PC)

Step 1 - Imaging

1. Put USB stick in PC.
 2. Power on Press F12 while booting to go into boot mode.
 3. Select boot option UEFI USB SanDisk
 4. On First Screen Select Backup.
 5. De- check the 480GB disk
 6. Check the one with several partitions.
 7. Select this disk.
 8. Select Image this Disk.
 9. Set destination folder to D:\
 10. Press Finish.
 11. It will take 15 to 20 mins.
 12. Close off Windows
 13. Remove USB stick
 14. Re-boot
-