

# TB0433 Incorrect Configuration of Air Service Unit


The main picture is correct- dial setting is visible

## Contents

Comments

This bulletin demonstrates the incorrect orientation of the pressure sensor dial on an air service unit. This is a regular supply issue. If an item is received like this, it must be returned to the supplier for replacement. If the unit is needed urgently, it will have to be dismantled and rebuilt correctly.

### Dial face



Incorrect- dial is not visible



Correct