

Fichier:RAG Report Mk2 Instructions Screenshot 2021-12-03 153626.jpg

Multihead Y and Z Axis		Check	Parts	Drawings	Note
Y axis - does it have full and smooth movement along all travel?		✓			
Y axis - are coupling grub screws tight?		✓			
Y axis - are the leadscrew and bearing in good condition?		✓			
Y axis - are the main load bearing shafts and bearings in good order?		✓			
Y axis servo motor - are cables in good order?		✓			
Y axis servo motor - are the plugs in good order? (no arcing evident or b...		✓			
Y axis - is the datum switch secure and in good working order?		✓			
Y axis - is the energy chain in good working order?		✓			
---- PARTS R0000714 Y Axis			9		

Subitems	Qty Rqd	Photo	Status	
B0000086 Ball Bearing 15 D 32 D 9 Long + seals	1		Urgent	
B0000139 Double Angular Bearing 20 D 47 D 20.6 Long + seals				
B0000236 90 Deg Grease Nipple M6 ST/ST				
C0000151 Samsung Servo Motor (X; Y; Z; Saw)				
D0006487 Y Stepper Housing				
D0006488 Y Leadscrew Sleeve				
D0008303 Servo Drive Coupling (Ø16)				
E0000079 Limit Switch - Roller Plunger	1		Important	
H0007789 Y Leadscrew				
+ Add Subitem				

Size of this preview: 705 × 599 pixels.

Original file (820 × 697 pixels, file size: 100 KB, MIME type: image/jpeg)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	18:27, 3 December 2021		820 × 697 (100 KB)	Gareth Green (talk contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

RAG Report Mk2 Instructions