

# Fichier:RAG Report Mk2 Instructions Screenshot 2021-12-03 153645.jpg

Multihead Y and Z Axis

	Check	Parts	Drawings
Y axis - does it have full and smooth movement along all travel?	✓		
Y axis - are coupling grub screws tight?	✓		
Y axis - are the leadscrew and bearing in good condition?	✓		
Y axis - are the main load bearing shafts and bearings in good order?	✓		
Y axis servo motor - are cables in good order?	✓		
Y axis servo motor - are the plugs in good order? (no arcing evident or b...	✓		
Y axis - is the datum switch secure and in good working order?	✓		
Y axis - is the energy chain in good working order?	✓		
----- PARTS R0000714 Y Axis		9	


R0000714.pdf

No higher resolution available.

RAG\_Report\_Mk2\_Instructions\_Screenshot\_2021-12-03\_153645.jpg (766 × 350 pixels, file size: 50 KB, MIME type: image/jpeg)

## File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	17:46, 3 December 2021		766 × 350 (50 KB)	Gareth Green (talk   contribs)	

You cannot overwrite this file.

## File usage

The following page links to this file:

RAG Report Mk2 Instructions