CNC Disk Drive FULL - Shadow Copies

Free up Space for a Disk Drive by removing Shadow Copy Files

| Difficulty Medium | Duration 5 minute(s) |

Contents

Introduction

Step 1 - Launch CMD line as administrator

Step 2 - Clear Shadow Copy Files

Comments

Introduction

When to use.

If when you need room on a disk TreeSize shows large usage in "System Volume Information"
Then use this procedure to remove the files.

Step 1 - Launch CMD line as administrator

Step 2 - Clear Shadow Copy Files

On the command line type

vssadmin Delete Shadows /ALL

Select YES when prompted.

Done