Autoflow PC Cleanup

How to clear up any temporary or historical files that may slow the PC down

| 🕑 Difficulty Medium	🕐 Duration 10 minute(s)

Contents

Step 1 - Close winSaw

Step 2 - Allow Hidden Items to be shown

Click the checkbox

Step 3 - Delete temp Appdata

User (Stuga) ---> 'Appdata' ---> 'Local' ---> 'Temp' - Delete everything within the 'temp' folder.

Step 4 - Delete Old Batches

This PC ---> 'Saw' ---> 'Archives' ---> Delete the .449 and .zeb files within this folder - this is removing the old batches