Fichier:AX5805 Dip Switch Settings.png

**4.4.3.2   Setting the TwinSAFE address of the AX5805/AX5806**

Fig. 2: DIP switch for setting the TwinSAFE address

You must set a unique TwinSAFE address using the 10-way DIP switch on the AX5805/AX5806 TwinSAFE drive option card. TwinSAFE addresses between 1 and 1023 are available. Address 0 is not permitted.

Size of this preview:800 × 581 pixels.

Original file (920 × 668 pixels, file size: 490 KB, MIME type: image/png)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	14:47, 15 August 2023		920 × 668 (490 KB)	Gareth Green (talk | contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

TB0406 Procedure to replace drive on TwinSAFE systems

Metadata

This file contains additional information, probably added from the digital camera or scanner used to create or digitize it. If the file has been modified from its original state, some details may not fully reflect the modified file.

Horizontal resolution	37.79 dpc
Vertical resolution	37.79 dpc