

# Fichier:Alarms form.png

Machine Settings

Datum Tests Accuracy Parameters Axes Tooling IO Map Clamps X Holds Alarms Profile Colours Notching Fine Adjustment

RefNo	Input Ref	iState	Output Ref	oState	Timeout	Action	Message	Module	Enblid	DemoH
1	InC_BmPosO	On	OuB_CLV	On	0	4-Abort	V Notching Attempted Bea...	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20	InF_AIR	On	<Undefined>	Off	50	3-Cycle...	Air Pressure Low	Both	<input checked="" type="checkbox"/>	<input type="checkbox"/>
32	InB_WOVL	On	<Undefined>	Off	0	3-Cycle...	Rear V overload Tripped	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
33	InB_VOVL	On	<Undefined>	Off	0	3-Cycle...	V Notch Motor Overload	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
41	InB_InvOk	Off	SPIN1	On	0	3-Cycle...	Spindle 1 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
42	InB_InvOk	Off	SPIN2	On	0	3-Cycle...	Spindle 2 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
43	InB_InvOk	Off	SPIN3	On	0	3-Cycle...	Spindle 3 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
44	InB_InvOk	Off	SPIN4	On	0	3-Cycle...	Spindle 4 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
45	InB_InvOk	Off	SPIN5	On	0	3-Cycle...	Spindle 5 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
46	InB_InvOk	Off	SPIN6	On	0	3-Cycle...	Spindle 6 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
47	InB_InvOk	Off	SPIN7	On	0	3-Cycle...	Spindle 7 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
48	InB_InvOk	Off	SPIN8	On	0	3-Cycle...	Spindle 8 Motor Alarm	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
52	SPHM1	Off	SPPL1	Off	20	3-Cycle...	Spindle 1 Not Home	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
53	SPHM2	Off	SPPL2	Off	20	3-Cycle...	Spindle 2 Not Home	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
54	SPHM3	Off	SPPL3	Off	20	3-Cycle...	Spindle 3 Not Home	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
55	SPHM4	Off	SPPL4	Off	20	3-Cycle...	Spindle 4 Not Home	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>
56	SPHM6	Off	SPPL6	Off	20	3-Cycle...	Spindle 6 Not Home	MH	<input checked="" type="checkbox"/>	<input type="checkbox"/>


Save

Size of this preview: 800 × 499 pixels.

Original file (913 × 570 pixels, file size: 83 KB, MIME type: image/png)

## File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	19:56, 21 January 2020		913 × 570 (83 KB)	Gareth Green (talk   contribs)	

You cannot overwrite this file.

## File usage

The following page links to this file:

Changing Control of Transfer to MH Side