

Fichier:GY GZ axis setup with Jetter Motors GY DRIVEMANAGER - 10.png

Manual velocity (fast): 30% of max motor speed	10	<input checked="" type="checkbox"/>	10	mm/s	300
Manual velocity (slow): 5% of max motor speed	2	<input checked="" type="checkbox"/>	2	mm/s	50
Calibration velocity (towards plc cam): 1% of max motor speed	10	<input checked="" type="checkbox"/>	10	mm/s	10
Calibration velocity (off plc cam): 1% of max motor speed	10	<input checked="" type="checkbox"/>	10	mm/s	10
Acceleration with an acceleration time of 1s	1500	<input checked="" type="checkbox"/>	1500	mm/s ²	1500
Deceleration with an acceleration time of 1s	1500	<input checked="" type="checkbox"/>	1500	mm/s ²	1500
Max allowed acceleration	15000	<input checked="" type="checkbox"/>	15000	mm/s ²	15000
Max allowed deceleration	15000	<input checked="" type="checkbox"/>	15000	mm/s ²	15000
Jerk with an acceleration time of 1s	4500	<input checked="" type="checkbox"/>	4500	mm/s ³	4500


Size of this preview:800 × 158 pixels.

Original file (2,025 × 399 pixels, file size: 387 KB, MIME type: image/png)

GY_GZ_axis_setup_with_Jetter_Motors_GY_DRIVEMANAGER_-_10

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	18:26, 9 March 2023		2,025 × 399 (387 KB)	Gareth Green (talk contribs)	GY_GZ_axis_setup_with_Jetter_Motors_GY_DRIVEMANAGER_-_10

You cannot overwrite this file.

File usage

The following page links to this file:

GY GZ axis setup with Jetter Motors

Metadata

This file contains additional information, probably added from the digital camera or scanner used to create or digitize it. If the file has been modified from its original state, some details may not fully reflect the modified file.

Horizontal resolution	56.69 dpc
Vertical resolution	56.69 dpc