

Fichier:R0000962E Bench assemble Y axis Components Screenshot 2024-01-05 083711.png

Z102 Snagging List 🔍 ☆

Main Table | Electrical | Outstanding Jobs | My Tasks | Electrical Testing | +

New Item AI Assistant Person Filter Sort Hide ...

▼ R0015139-OH Module B Machining Centre

Item	Subitems Status	Sign Off	Link	Link 2	Assign
▼ R0000971E Bench Assemble R Axis Gearbox 2			https://stuga.doki...		ML
Subitem	Status	Sign Off	Issue Status	Issue Description	Issue Files
Carry Out QC Check		Not Required			Add/Manage files
D0000268 rotary pulley		Not Required		damage to part	+
+ Add subitem					
+ Add Item					ML

+ Add new group


Size of this preview: 800 × 441 pixels.

Original file (1,269 × 699 pixels, file size: 84 KB, MIME type: image/png)

R0000962E_Bench_assemble_Y_axis_Components_Screenshot_2024-01-05_083711

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	10:42, 5 January 2024		1,269 × 699 (84 KB)	Gareth Green (talk contribs)	R0000962E_Bench_assemble_Y_axis_Components_Screenshot_2024-01-05_083711

You cannot overwrite this file.

File usage

There are no pages that link to this file.

Metadata

This file contains additional information, probably added from the digital camera or scanner used to create or digitize it. If the file has been modified from its original state, some details may not fully reflect the modified file.

Horizontal resolution	37.79 dpc
Vertical resolution	37.79 dpc