

Fichier:Stuertz Welder - Setting Barcode Reader Screenshot 2022-09-28 151142.jpg

Procedure:

1. Install the **downloaded** file.
2. **Reboot** the host.
3. **Scan** the following barcode.

USB - CDC Host



4. Now, your scanner should show up in Device Manager with a COM port number.


Size of this preview:800 × 432 pixels.

Original file (927 × 501 pixels, file size: 64 KB, MIME type: image/jpeg)

Stuertz_Welder_-_Setting_Barcode_Reader_Screenshot_2022-09-28_151142

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	16:13, 28 September 2022		927 × 501 (64 KB)	Gareth Green (talk contribs)	Stuertz_Welder_-_Setting_Barcode_Reader_Screenshot_2022-09-28_151142

You cannot overwrite this file.

File usage

The following page links to this file:

Stuertz Welder - Setting Barcode Reader