

# Input Definition 003 - InA Measure2

---


Input Definition 003 - InA\_Measure2

## Contents

Comments

[Back To Stuga Machine IO Dictionary - Inputs](#)

[See Input Definition 002 - InA Measure1](#)

 ...This input is not used in the software

The original design intent was to use two sensors to double check the measurement, but this proved unreliable in practice. Only sensor 1 input is used.

it is common practice to swap the input cable from 1 to 2 if sensor 1 fails - this is an easy "over the phone" fix