

R0015033B ZX5 Module F Wiring Loom

Information to install cable looms

 Difficulty **Medium**

 Duration **4 hour(s)**

Contents

Introduction

Step 1 - Ethercat box connections

Step 2 - Ethercat box connections

Comments

Introduction

Tools Required

Flush cutters
Reed switch testing box
Standard hex keys

Parts Required

Step 1 - Ethercat box connections

Connect ethercat power cables



Step 2 - Ethercat box connections

