

Sales Document - Main Linear Rails

Replacement linear rail option details


Contents

Details
Disclaimer
Comments

Summary	Design lifetime for the racks is 10 years. Replace the Machine side and saw slide main rail sideways, journals and sprockets.
Advantages	Removes backlash and misalignment due to wear providing a more stable platform for reliable accuracy.
Applies to	All
Prerequisites Required	None
Customer Site Installation?	Yes
Order Code	R0009550 Flowline (-60 for 6.0m, -65 for 6.5m) R0009551 ZX3/4 (-60 for 6.0m, -65 for 6.5m)
Down Time	2 days

Details

- Replace 2 off 7m-8m rails on machine complete with journal bearings and drive sprockets
- Recalibration and accuracy testing



Disclaimer

Accuracy problems are complex and are generated by many root causes, rack wear is only one of them. This upgrade is not guaranteed to solve all issues related to machine accuracy.

