

TB0420 Obsolescence Note - Flowline Spindle Motors

The original motor is no longer available, and a replacement has proved impossible to find due to the physical size of the motor

Contents

Parts Affected

Comments

Parts Affected

The original motor is no longer available, and a replacement has proved impossible to find due to the physical size of the motor.

The design constrains the frame size, and requires two modifications

1. Fins on the motor need to be machined off to prevent the motor casing hitting the infeed clamps
2. The motor electrical connection box needs to sit in the correct orientation and be physically low enough to pass underneath the spindle connection box. A modified lid was fitted to allow this to happen

All replacements considered cannot meet these physical constraints, particularly the connection box issue.

Stuga have a small stock of second-hand motors. The recommendation is to get the motors rewound locally to the customer site – Stuga are unable to offer this service.



Part Nos	Description
D0008252	Std Hand
D0007342	Opp Hand
E0000219	Original Motor 71/B14 2 Pole 0.75kW

