Upgrade - MH Spindles for Flowline

This new assembly (R0000164B) covers replacement spindles for MH on Flowlines etc

Contents

Comments

There was a need to update how to upgrade these spindles when they fail, in the field.

An upgrade had been created in 2018, but it required buying in a part and then machining it. This added an unnecessary and expensive process, so a further redesign has been done. This now uses a standard bought in part (T0000203), and the mating part (D0006016B) has now been created which provides an exact form, fit and function replacement to the overall assembly. Assembly of the components is as per the exploded view

