

ZX5-11 Conveyor Pinch Point


Compliance upgrade to remove hazard of finger trap on conveyor

Contents

Method

Comments

Method



ensure gap is less than 5mm between nozzle and belt then fit a 3 mm roll pin drilled through both parts to stop bolts acting as a pivot