

# WinMulti - Changing The Colour Identification Box

How to use the colour identification box to indicate profile colour and loading orientation



Difficulty **Very easy**



Duration **1 minute(s)**

## Contents

Introduction

Step 1 - Method 1 - Via Settings Tab

Step 2 - Method 2 - From Bar Queue

Comments

## Introduction

The version 6 software has a feature to identify the colour of the profile and also to help operators load foiled profile in the correct orientation.

Updating the colours is a very simple job that can be done in 2 ways




1. Via the Machine Settings->Colours Tab
2. From Bar Queue whenever a new colour is encountered.

## Step 1 - Method 1 - Via Settings Tab

1. Open Settings->Colours
2. Select the colour from the list
3. Update the Description if required
4. Edit the Top, Core and Face colour by clicking and choosing a colour



...The colour codes are automatically added each time a new colour code is sent to the machine



## Step 2 - Method 2 - From Bar Queue

Click on the Colour Indicator bar next to the profile picture  
The colour settings tab will open as Method 1, but the colour will be automatically selected

