

Outfeed Support Roller - Flowline

Part code R0010276 - Extra support roller upgrade added to replace single roller on outfeed rear clamp.

Contents

Comments

A primary reason for this upgrade is to avoid the single roller falling into the gap of a wide V notch. It also gives better support when clamping profile on the outfeed of the MultiHead.

Images below show the single roller:





Below are images of the Double fitted roller :

