TwinCAT3 Licensing

How to License a Beckhoff PC for running TwinCAT3

Contents

CF Card has been swapped and licence needs renewing

PLC Supplied without a Licence

If Beckhoff Server Refuses you a Licence

Comments

CF Card has been swapped and licence needs renewing

For aging PCs, the CF card may need renewal and often this is done by sending a CF card from HQ. In this case, the licence that was used to set the PC up will not be valid until it is processed by the servers at Beckhoff. You will need to request a new licence

Click here for Beckhoff's instructions on licensing

PLC Supplied without a Licence

If the Beckhoff PCs are supplied without a licence, the TwinCAT instance will not run and there will be an error about "licence missing" This problem can be crated if the licence is not ordered at the same time as the PC.

Beckhoff allow anytime Temporary licenses, but they only last for 7 days. This is useful if you need to get up and running and leave the licencing proper for when there is more time available

Click here for Beckhoff's instructions on licensing

... The licence file is expensive, so should only be ordered if you are certain that the licence has not been ordered for the PC you are having an issue with. Double check the serial number of the PC with Beckhoff

Order Codes for TwinCAT3 Licenses

PC	Order Code	Description	
CX512	C0001130	TC1250-0040 TwinCAT3 Licence PtP	
C6015	C0001130B	TC1250-0050 TwinCAT3 Licence PtP	

If Beckhoff Server Refuses you a Licence

Could you add the TC1250 license instead of TC1200+TF5000. They are identical but can confuse the server at times.

Solution Explorer 🔷 부 🗙	C S093B 🕂 X Version_Info			
0 0 🟠 jo - 🗊 🔑 🗕	Order Information (Runtime)	anage Licenses Project Licenses Online Licenses		
Search Solution Explorer (Ctrl+;)	Disable automatic detection	n of required licenses for project		
G. Solution 'S093B' (1 project)	Order No	License	Add License	<u>_</u>
SYSTEM	TC1000	TC3 ADS	Cpu license	
License	TC1100	TC3 IO	Cpu license	
▷ 🧼 Real-Time ▷ 🎁 Tasks	TC1200	TC3 PLC	🗸 cpu license	
afin Routes	TC1210	TC3 PLC / C++	cpu license	
Type System	TC1220	TC3 PLC / C++ / MatSim	Cpu license	
TcCOM Objects	TC1250	TC3 PLC / NC PTP 10	🗸 cpu license	
MOTION	TC1260	TC3 PLC / NC PTP 10 / NC I	cpu license	
A PLC	TC1270	TC3 PLC / NC PTP 10 / NC L / CNC	C cpu license	