

Fichier:Peripheral Voltage Check.png

Channel A >> Diagnostics >> Error history

Operating time drive control (S-0-0435): 30692h 19m 53s Export list

ErrorTime	ErrorCode	ErrorMessage	
30688h 28m 38s	0x0000FD43	Mains supply: Power down.	?
30688h 28m 37s	0x0000FD4B	DC link undervoltage.	?
30683h 49m 47s	0x0000FD43	Mains supply: Power down.	?
30683h 49m 46s	0x0000FD4B	DC link undervoltage.	?
30681h 3m 14s	0x0000FD43	Mains supply: Power down.	?
30681h 3m 14s	0x0000FD4B	DC link undervoltage.	?
30672h 58m 3s	0x0000FD43	Mains supply: Power down.	?
30672h 58m 3s	0x0000FD4B	DC link undervoltage.	?
30670h 57m 3s	0x0000FD43	Mains supply: Power down.	?
30670h 57m 3s	0x0000FD4B	DC link undervoltage.	?
30664h 24m 31s	0x0000FD43	Mains supply: Power down.	?
30664h 24m 31s	0x0000FD4B	DC link undervoltage.	?
30661h 19m 54s	0x0000FD43	Mains supply: Power down.	?
30661h 19m 54s	0x0000FD4B	DC link undervoltage.	?


Diag Msg	Umain OK	DcLink OK	Ampl. Te...	Actual op...	v <= v_0	Positive c...	Negative ...	Periph. Vo...
Axis state machine...	●	●	47.1	2: velo control	●	●	●	21.629
Axis state machine...	●	●	48.3	2: velo control	●	●	●	21.629

Size of this preview: 800 × 474 pixels.

Original file (850 × 504 pixels, file size: 291 KB, MIME type: image/png)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	20:12, 4 December 2019		850 × 504 (291 KB)	Gareth Green (talk contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

Beckhoff Servo Drive Error Diagnosis