

Fichier:Stuga Batch Cutting List Specification Annotation 2019-09-20 140500.jpg

```
B, Test23rd.449, S
L, BLR56E, WHITE, 1, 60000,
P, 12340, \/, 00, 00, BR129A/001
P, 12340, \/, 00, 00, BR129A/001
P, 20000, \/, 00, 00, BR129A/001
O, 00100, DFR, 000, 000, 000
O, 00150, DRR, 000, 000, 000
O_100000_F.SP_000_000_000
```


No higher resolution available.

Stuga_Batch_Cutting_List_Specification_Annotation_2019-09-20_140500.jpg (779 × 413 pixels, file size: 88 KB, MIME type: image/jpeg)

Stuga_Batch_Cutting_List_Specification_Annotation_2019-09-20_140500

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	15:05, 20 September 2019		779 × 413 (88 KB)	Gareth Green (talk contribs)	Stuga_Batch_Cutting_List_Specification_Annotation_2019-09-20_140500

You cannot overwrite this file.

File usage

The following file is a duplicate of this file (more details):

Fichier:Recovery of Bar Queue following winMulti Crash Annotation 2019-09-20 140500.jpg

The following page links to this file:

Stuga Batch Cutting List Specification