


Fichier:Xhold after.png



The screenshot shows a 'Machine Settings' dialog box with a tabbed interface. The 'Datum Tests' tab is active, displaying a table with the following data:


Output	lowLimit	highLimit	Axis
OuB_VCut	-10000	800	X
OuB_CLV	-10000	1080	X
<Undefined>	-10000	820	X
<Undefined>	-10000	950	X
SPPL1	-10000	50	X
SPPL2	-10000	50	X
SPPL3	-10000	50	X
SPPL4	-10000	50	X
SPPL5	-10000	50	X
SPPL6	-10000	50	X
SPPL7	-10000	50	X
SPPL8	-10000	50	X
SPDP3	-10000	50	X
SPDP7	-10000	50	X

No higher resolution available.

Xhold_after.png (540 × 553 pixels, file size: 98 KB, MIME type: image/png)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	14:59, 9 August 2023		540 × 553 (98 KB)	Gareth Green (talk contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

Root Cause Analysis - Tool break when spindle not starting at beginning of bar

Metadata

This file contains additional information, probably added from the digital camera or scanner used to create or digitize it. If the file has been modified from its original state, some details may not fully reflect the modified file.

Horizontal resolution	56.69 dpc
Vertical resolution	56.69 dpc