

Fichier:RAG Report Mk2 Instructions Screenshot 2021-12-03 153727.jpg

Subitems		Qty Rqd	Photo	Status	
B0000086 Ball Bearing 15 D 32 D 9 Long + seals		1		Urgent	
B0000139 Double Angular Bearing 20 D 47 D 20.6 Long + seals					
B0000236 90 Deg Grease Nipple M6 ST/ST					
C0000151 Samsung Servo Motor (X; Y; Z; Saw)					
D0006487 Y Stepper Housing					
D0006488 Y Leadscrew Sleeve					
D0008303 Servo Drive Coupling (Ø16)					
E0000079 Limit Switch - Roller Plunger		1		Important	
H0007789 Y Leadscrew					
+ Add Subitem					

No higher resolution available.

RAG_Report_Mk2_Instructions_Screenshot_2021-12-03_153727.jpg (756 × 397 pixels, file size: 51 KB, MIME type: image/jpeg)

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	17:49, 3 December 2021		756 × 397 (51 KB)	Gareth Green (talk contribs)	

You cannot overwrite this file.

File usage

The following page links to this file:

RAG Report Mk2 Instructions